Rosemary Fon, Tomble Fon (Manager's Residence, Men's Dormitory, Barn, 8ldg. No. 373) Olympic National Park Barnes Point, Lake Crescent Port Angeles Vicinity Clallam County Washington HABS No. WA-185-B

HABS WASH 5-POANN, AB-

## PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA


Historic American Building Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107


## NATIONAL PARK SERVICE Department of the Interior

## HISTORIC AMERICAN BUILDING SURVEY ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VIC	<b>CINITY</b> ely 20 miles southwest of
WASHINGTON	CLALLAM	Port Ange	les
HISTORIC NAME OF STRUCTU	RE (include source for na	me)	HABS NO.
Rosemary Inn, Tum	ble Inn (Historic Stru	cture Report)	WA-185-B
SECONDARY OR COMMON NA	MES OF STRUCTURE		<u> </u>
Manager's Residence; Men'	s Dormitory; Barn (HSR	, 1986) <sub>;</sub> B1dg.	No. 373
from Port Angeles, in Oly	e of Lake Crescent, noŕ mpic National Park.	th side of Hwy	101, approximately 20 miles
DATE OF CONSTRUCTION (inc	lude source) ARC	<b>CHITECT(S) (Inclu</b> Builder and Cr	ide source) aftsman:
Late 1920s (Historic Stru	icture Report)	John Daum (HRS	<b>,</b> 1983)
as the residence of the r	ructed as an integral p resort manager in the l the overall character o	art of the Ros 940s and 1950s f the rustic,	emary Inn Complex. It served, and possibly earlier. The picturesque resort ensemble, cation, setting, feeling and
"Dutch Colonial" style co	ttage		
MATERIAL OF CONSTRUCTION		me)	
Wood-frame construction s	•	•	iers.
SHAPE AND DIMENSIONS OF S	STRUCTURE (sketched floo	or plans on separ	rate sheet acceptable)
	dimensions 31' x 38'	•	,
supported by knee braces:	ngled gambrel roof wit clapboard siding with on on west; hip-roofed	wood shingles entry porch o	rmer on west; extended eaves above (at gable ends); n south facade; multi-paned
INTERIOR FEATURES OF NOTE	•		
Fir floors; exposed beams below with 5" vertical bo	in living room with 7 Pards above; peeled log	" wood boards; bannister lea	walls are 7" vertical boards ding to second floor.
	DITIONS WITH DATES		
is possibly an addition,	on on west facade (now date unknown.	housing secti	on of kitchen and a bathroom)
PRESENT CONDITION AND US	Ē		
Fair; Vacant			
OTHER INFORMATION AS APP	ROPRIATE		
SOURCES OF INFORMATION (in Historic Structure Report Historic Resource Study, Historic Building Invento	;, 1986 1983	Register, State R National R	<b>legisters, etc.)</b> egister Listing, 1979
COMPILER, AFFILIATION			DATE
Gretchen A. Luxenberg, Na	ational Park Service		July, 1988

ROSEMARY INN, TUMBLE INN (Manager's Residence, Men's Dormitory, Barn, Bldg. No. 373) HABS No. WA-185-B (page 2)





second Floor

